

Silver Pulser SP5

Micropulsing Troubleshooting






Silver Pulser SP5 Micropulsing Troubleshooting







The Yellow Micropulsing
Light and the Orange
Ionic~Colloidal Silver Light
are both on.

Please stop using the unit, as there is a fault with either the Micropulsing Cord or the unit. Contact Customer Experience at 1.800.224.0242

or repairs@sota.com