






Silver Pulsar SP5

Ionic~Colloidal Silver Troubleshooting





Silver Pulsar SP5

Ionic~Colloidal Silver Troubleshooting

**Black Particles
(Silver Oxide) are
present in the Water.**

The particles can be filtered out (a coffee filter works well). The following are suggestions to help minimize Silver Oxide:

Stir the solution periodically during the process.

Periodically, clean the Silver Wires with a paper towel during the process.

Ensure Distilled water is being used.

Be sure the Silver Wires are not touching the glass and are at least one inch from the bottom of the glass.